AGENDA REGULAR DRAINAGE MEETING DECEMBER 5, 2018 12:00 NOON

- 1. Open Meeting
- 2. Approve Agenda
- 3. Approve Minutes

 November 28, 2018 Regular Drainage Meeting

Documents:

11_28_2018 - DRAINAGE MINUTES.PDF

4. DD 41 - Discuss, With Possible Action, Investigation Summary Of Request For Acres Of Watershed Boundary Parcels

Documents:

6682.2_INVESTIGATION_SMMARY_2018_12_03.PDF

5. DD 52 - Approve Petition To Expand Right Of Way

Documents:

PETITION TO EXPAND RIGHT OF WAY OF DRAINAGE DISTRICT.PDF

 DD 55-3 Lat 9 - Discuss, With Possible Action, Investigation Summary For Work Order #224

Documents:

DD55-3LAT9WO224.PDF

7. DD 143 - Discuss, With Possible Action, Investigation Summary For Hearing Action Items

Documents:

DD143-HEARING ACTION ITEMS.PDF

8. DD 148 - Discuss, With Possible Action, Repair Summary For Work Order #211

Documents:

DD148WO211-2018-12-3.PDF

- 9. DD 148 Approve Engineer's Report On Repairs To Open Ditch
- 10. DD 26 Discuss, With Possible Action, Utility Permit #2018-13 With Radcliffe Telephone

Documents:

5055.1_INVESTIGATION_SUMMARY-2018_12_04.PDF

11. DD 124 - Discuss, With Possible Action, Investigation Summary For Utility Permit #2018-8 Documents:

DD124PERMIT2018-8.PDF

12. DD H-F 1 - Discuss, With Possible Action, Investigation Summary For Utility Permit #2018-

Documents:

- 13. Other Business
- 14. Adjourn Meeting

REGULAR DRAINAGE MEETING

11/28/2018 - Minutes

1. Open Meeting

Hardin County Board of Supervisor Chairman, BJ Hoffman, opened the meeting. Also present were Supervisors, Lance Granzow and Renee McClellan; Hardin County Attorney, Darrell Meyer; Contractor, Jacob Handsaker with Hands On Excavating; Lee Gallentine with Clapsaddle-Garber Associates (CGA); Drainage Clerk, Tina Schlemme.

2. Approve Agenda

McClellan moved, Hoffman seconded to approve the agenda as presented. All ayes. Motion carried.

3. Approve Minutes

McClellan moved, Hoffman seconded to approve the minutes of the November 14, 2018 regular drainage meeting. All ayes. Motion carried.

4. Approve Claims For Payment

McClellan moved, Hoffman seconded to approve the claims for payment with pay date of Friday, November 30, 2018. All ayes. Motion carried.

DD H-S 3-58 Assessments 2018	Story County Auditor	\$	943.90
DD H-H 1-103 ASSESSMENTS 2018	Hamilton Co Auditor	\$	781.00
DD H-F 4-53 ASSESSMENTS 2017	Franklin Co Auditor	\$	6.00
DD 22 ENG SVCS 9/15-10/20/18	Clapsaddle-Garber Assoc	\$	660.00
DD 55-3 LAT 9A WO 29 ENG FEES	Clapsaddle-Garber Assoc	\$	544.65
DD 136 WO 146 POSTAGE	Hardin County Auditor	\$	7.98
DD 25 CANCEL CONTRACT BONDING COSTS	SFarm Tile Pro LC	\$5	,336.00
DD 52 Legal Advice for filing petition	The Davis Brown Law Firm	\$	57.00
DD 148 WO 211 Repair	R D Customs LLC	\$	967.00

5. DD 41, 77, 123, 128, 143 & Big 4 Main - Approve Change Order #2

Hoffman stated there were concerns with Hands On completing some municipal projects and not working on the contracted drainage projects to meet the deadline. Handsaker replied that due to the weather, they were only able to work on the municipal projects because they were rock surfaces. They completed the streets and waterway drainage projects but did not get the excavator work done due to wet soil conditions. He added that they were hoping to get it done yet this winter or early spring. McClellan moved, Hoffman seconded to approve Change Order #2 for a time extension from November 30, 2018 to May 1, 2019. All ayes. Motion carried.

6. DD 48 - Approve Work Order Request #237

McClellan moved, Granzow seconded to approve Work Order Request #237 for an outlet problem in section 23-88-21. CGA is to investigate and report back. All ayes. Motion carried.

7. DD 21 - Approve Work Order Request #239 For Reclassification

McClellan moved, Granzow seconded to approve Work Order Request #239 for a reclassification to result as discussed at the June 13, 2018 regular drainage meeting. All ayes. Motion carried.

8. DD 9 - Discuss, With Possible Action, Updates To Work Order #229

Gallentine presented a few problems discovered: 1) Trees in the RR right of way with some water flow on the south track crossing of the main tile. 2) A sinkhole in/near RR right of way with fiber optic warning tape in hole. Tile 1/2-3/4 full of dirt and rock and no water flow on the north track crossing of the main tile. 3) A sinkhole in field with tile 1/4-1/2 full of dirt and sand and some water flow on the main tile east of tracks. A couple options were discussed, both being over \$50,000. McClellan moved, Granzow seconded for CGA to prepare an engineer's report. All ayes. Motion carried.

9. Discuss, With Possible Action, Drainage Clerk Position

Much discussion was had regarding changing the drainage clerk position to a full-time position under the Board of Supervisors. Meyer submitted Code of Iowa sections pertaining to drainage clerk position. After many ideas were discussed, the Trustees agreed for Meyer to draft an agreement between the Auditor and the Board. The position will begin January 1, 2019 and the clerk will then track all time spent on drainage districts, which will be assessed to the districts annually based off of the calendar year. The current budget will be used for January 1, 2019 to June 30, 2019 and then 100% of the salary will be taken out of a new line item under the Board from the general fund and will be reimbursed when assessments are collected (first collecting in 2020). The Trustees understood that the salary would not be 100% reimbursed due to general administrative duties.

10. Other Business

DD 55-3 Lat 12 - Schlemme updated the Trustees that the Notice of Repair Across Railroad Right-of-Way was mailed to the UPRR on September 27, 2018, giving them 30 days notice. Granzow moved, McClellan seconded to perform the additional actions recommended of removing the trees within 50 feet of the tile, root cleaning and jetting the lateral tile and televising the lateral to verify the condition, as shown in the Repair Summary for Work Order #201. All ayes. Motion carried.

11. Adjourn Meeting

Granzow moved, McClellan seconded to adjourn the meeting. All ayes. Motion carried.

#41

Investigation Summary:

- District Trustees requested that the SW¼ and NW¼ Section 8, Township 88 North, Range 21 West be investigated to determine the number of acres of each that are within the Drainage District watershed.
- CGA staff performed site visit and topographic survey to determine drainage boundary in the same.
- Using this field data and Lidar elevation data, CGA staff drafted contour maps (copies attached) showing drainage district boundaries and computed areas for the SW¼ and NW¼ that are within the drainage district boundaries by surface drainage.


Contractor Time and Materials (spent while CGA was on-site):


None recorded as only investigation was performed.

Additional Actions Recommended:

- Based on the attached maps, it is clear that the SW¼ and NW¼ surface drain towards the drainage district and portions of each should be included in the drainage district.
- The District Trustees should compare the number of acres shown on the maps to those in the existing classification to see if an inequity exists.
- If one does exist, it is recommended that the District Trustees seek legal advice on how to rectify it (i.e. reclassification or some other method).







HARDIN COUNTY AUDITOR HARDIN COUNTY DRAINAGE DISTRICT

In re Hardin County Drainage District No. 52 by and,	
Petitioner,	PETITION TO EXPAND RIGHT OF WAY OF DRAINAGE DISTRICT 52
VS.	PURSUANT TO IOWA CODE § 468.139
Piel Manufacturing Company, Inc.	
Respondent.	
TO THE COUNTY AUDITOR HARDIN CO	
52 Pursuant to Iowa Code § 468.13	ners and Petition to Expand Right of Way of Drainage District 39. ask that the drainage commencing at
The undersigned sets forth the facts a	s the following:
1. Drainage District No. 52 in I	Hardin County was a properly established drainage
district pursuant to Iowa law.	
2. The Board of Trustees overse	es the maintenance of Drainage District No. 52, and
is legally obligated to maintain the tile.	
3. In 2010, Drainage District	52 experienced multiple maintenance and repair
requests due to problems caused from certain	in tree roots being in the tiles. Piel Manufacturing
Company, Inc. ("Piel Manufacturing"), in	Hubbard, Iowa, is the owner of the trees and the
property where the trees are located.	
4. The location of the trees wh	ich were causing the problem are at the following
location (legal description):	

A tract of land located in Lots Two (2) and Three (3) of County Auditor's Sixth Plat in the East One-half of the Northeast Quarter (E½ NE¼) of Section Thirty-three (33), Township Eighty-seven (87) North, Range Twenty-one (21) West of the 5th P.M., being within the City of Hubbard, Hardin County, Iowa, more particularly described as follows:

Commencing at the Northwest Corner of said Lot 3; thence South 83°31'52" East, 577.25 feet along the north lines of said Lots 3 and 2 to the point of beginning; thence South 83°31'52" East, 44.50 feet along said north line of said Lot 2; thence South 00°51'00" West, 189.75 feet; thence North 89°06'56" West, 173.25 feet; thence North 81°25'47" West, 154.00 feet; thence North 01°54'11" West, 42.00 feet; thence North 89°20'31" East, 273.00 feet; thence North 05°45'56" East, 124.64 feet to the point of beginning, containing 0.60 acres total. Subject to easements.

Note: For the purposes of this easement, the north line of said Lots 2 and 3 was determined to bear South 83°31'52" East using GPS.

- 5. In 2010, 300 feet of tile was replaced with non-perforated water tight gasketed HDPE tile. The new tile was also relocated to be further away from the trees.
- 6. Now, in 2018, the problem is reoccurring, and the tree roots have protruded through the non-perforated tile, again causing blockages in the tile.
- 7. A contractor was able to get the roots pulled out and the tile flowing again, but the tree roots will continue to cause overflow to the tile.
- 8. The removal of the trees is necessary to prevent the tile from further and future obstruction.
- 9. Drainage District 52's easement should be expanded to include the aforementioned legal description where the trees are located and to remove the trees, pursuant to Iowa Code § 468.139.
 - 10. The removal of the trees is authorized by Iowa Code § 468.139.
- 11. The Board of Trustees has requested that Piel Manufacturing consent to the removal of the trees. Piel Manufacturing has refused.

- 12. Pursuant to Iowa Code the Drainage District has an obligation to make sure that the tree roots do not impeded the flow of water in the drainage tiles. As such, the undersigned request that the Board destroy and remove the trees obstructing the tile.
- 13. It is necessary to destroy the trees or hedges outside the current right-of-way to prevent the tiles from obstruction by the roots. The board and the owners of such trees or hedges cannot agree upon the damage for the destruction thereof, and the board is hereby proceeding to acquire the right to destroy and remove such trees for the public benefit, utility, health, convenience, and welfare which will be promoted by the aforementioned project.
- 14. Undersigned hereby moves the Auditor to convene the parties for proceedings related to the same.
 - 15. Undersigned hereby moves the Auditor to consider whether bond is appropriate.
- 16. Undersigned moves for the County Engineer to prepare a report to present to the Board of Trustees to expand the right away as proposed herein, for notice of a hearing, and for an adjudication related to the same.



Drainage Work Order Request For Repair Hardin County


Date:	8/9/2018	
Work Order #:	WO00000224	
Drainage District:	Drainage Districts \DD 55-3 (51085)\DD 55-3 La	t 9(5124
Sec-Twp-Rge:	01-86-20 Qtr Sec: NE1/4	
Location/GIS:	86-22-01-200-001	
Requested By:	Randy Dubberke	
Contact Phone:	(641) 864-3388	-
Contact Email:	randeb@netins.net	·
Landowner (if different):	RanShell, LLC	
Description:	Outlet seems plugged and land from NE1/4 Section district boundaries but draining into DD) overflow ditch lying east of H Avenue.	v i i i i i i i i i i i i i i i i i i i
Repair labor, material	s and equipment:	
Repaired By:		Date:
Repaired by.		Date.
Please reference work	order # and send statement for services to:	Hardin County Auditor's Office Attn: Drainage Clerk 1215 Edgington Ave, Suite 1 Eldora, IA 50627 Phone (641) 939-8111 Fax (641) 939-8245
For Office Use Only		•
Approved:		Date:

Auditor's Office Hardin County 0.035

0.28 Miles

Date: 8/9/2018





42000-862201100002 Granzow, Marcia K. Granzow, Mark 34.79 acres 18143 Co Hwy D47



Wiechmann, Kaylissa Arni 22,09 acres 1121 N Frement Apt 2

42000-862201200003 Ran-Shell, LLC 40 acres 28767 I Ave

(A20110) A8 TA

42000-862201100005 Granzow, Marcia K Granzow, Mark 40 acres 18143 Co Hwy D47

Mark


42000-862201100004 zow, Marcia K Granzow, M 39 acres 18143 Co Hwy D47

LAT 9 (Olnch)

1350



39000-872236300003 Miller, Keith A Miller, Jean M 37.59 acres 24525 Co Hwy S33



#55 Division 3 Lateral 9

Investigation Summary:

- Landowner indicated that surface water from the NE¼ Section 2 and NW¼ Section 1, Township 86 North, Range
 West was flowing from outside of the Lateral watershed boundary into district Lateral facility.
- CGA staff performed site visit and didn't find any visible evidence of the above claim.
- Using Lidar elevation data, CGA staff drafted contour map (copy attached) showing surface water Lateral watershed boundary and inserted record (1981/recent reclassification) version of the same.


Contractor Time and Materials (spent while CGA was on-site):

None recorded as only investigation was performed.

Additional Actions Recommended:

- Based on the attached map, it is clear that the above mentioned versions of the Lateral watershed boundary
 vary from each other as they overlap one another slightly in different directions. However, the net effect in
 Section 1 is an excess of 0.66 acres in the Lateral drainage area and the net effect in Section is a shortage of
 0.65 acres in the Lateral drainage area.
- The District Trustees should decide if this area is large enough that an inequity exists.
- If one does exist, it is recommended that the District Trustees seek legal advice on how to rectify it (i.e. reclassification or some other method).





143

Investigation Summary:

- At the Hearing on Engineer's Report for Repairs to Upper End of Main Tile, the District Trustees requested an investigation of who owned the fiber optic utilities that were bored through the Main Tile.
- Based on information from the Iowa One-Call service, it appeared that the most likely utility at issue was Radcliffe Telephone Company.
- Contacted Radcliffe Telephone Company via telephone on November 11, 2018 and they indicated that they use orange conduit for their fiber optic line.
- Attached photographs (Pic #1 and Pic #2) from CCTV inspection clearly show that conduit bored through the Main Tile is orange. The locations of said fiber optic lines being bored through the Main Tile are shown on the attached CCTV Investigation Map.


Contractor Time and Materials (spent while CGA was on-site):

None as only investigation was performed.

Additional Actions Recommended:

Radcliffe Telephone Company should remove their fiber optic lines from the Main Tile and repair the Main Tile at these two locations. The repair should be observed, documented, and performed to applicable Drainage District standards. It is CGA's opinion that this should be done at no cost to the drainage district unless there is an agreement or lowa Code section that states otherwise.





491.7 ft. П 11:09:44 AM 491.7 PP. 2/22/2017

Pipe material: Foliary

143

Investigation Summary:

- At the Hearing on Engineer's Report for Repairs to Upper End of Main Tile, the District Trustees requested an inventory of trees within the 50' of the Main Tile from the west end of town to the east end of town (i.e. west side of the golf course) be performed.
- CGA staff performed a site visit along the Main Tile route and found the following trees within 50' of the Main Tile (unless noted otherwise):
 - o 3 Walnuts (28"-36")
 - o 1 Buckeye (12")
 - o 3 Oak (6"-36")
 - 12 Brush or Brush Lines
 - o 1 Cedar (24")
 - o 4 Blue Spruce (8"-15")
 - o 13 Apple (2"-24")
 - 2 Honey Locusts (24"-36")
 - o 10 Ash (10"-48")
 - o 4 River Birch (24"-36")
 - 22 Soft Maple (2"-48")
 - o 12 Hard Maple (8"-48")
 - o 3 Mulberry (6")
 - o 1 Boxelder (24")
 - o 1 Sycamore (48") at 54' from tile

Contractor Time and Materials (spent while CGA was on-site):

None as only investigation was performed

Additional Actions Recommended:

Although all trees are capable of producing tree roots which can negatively impact tile, the above yellow highlighted trees species are some that we typically find majorly impacting tile negatively. If the District Trustees do not pursue lining the Main tile, they may wish to pursue removal of at least the yellow highlighted trees as it is CGA's opinion that they will eventually (or may already be) negatively impacting the Main Tile. It is also our opinion that the cost of removal of just these trees would be over \$50,000. This cost is high enough that a hearing and engineer's report would be required.



143

Investigation Summary:

At the Hearing on Engineer's Report for Repairs to Upper End of Main Tile, the District Trustees requested an opinion of probable construction cost to line the existing Main tile from the west end of town to the east end of town (i.e. west side of the golf course).

Contractor Time and Materials (spent while CGA was on-site):

None as only investigation was performed

Additional Actions Recommended:

Based on conversations with some lining companies and recent bid letting for sanitary sewer lining, CGA drafted the attached Engineer's Opinion of Probable Construction Costs. Said opinion is just below \$500,000. This cost is high enough that a hearing and engineer's report would be required.






By: Z.J.S.

Date: 11/21/2018
Checked By: L.O.G.
Date: 11/21/2018

Engineer's Opinion of Probable Construction Costs Project: Main Tile for D.D. #143 Location: City of Radcliffe, Hardin County, Iowa

	ITEM#	DESCRIPTION	U	nit Cost	Units	Quantity	Units	Total Cost
		CONSTRUCTION COSTS						
	101	TILE CLEANING	\$	5.00	LF	4609	LF	\$ 23,045.00
	102	14-INCH TILE LINING	\$	35.00	LF	1315	LF	\$ 46,025.00
(n	103	18-INCH TILE LINING	\$	50.00	LF	2558	LF	\$ 127,900.00
LINING	104	20-INCH TILE LINING	\$	60.00	LF	736	LF	\$ 44,160.00
N	105	ACCESS MANHOLES	\$ 1	0,000.00	EA	9	EA	\$ 90,000.00
	106	REINSTATE TAP	\$	200.00	EA	87	EA	\$ 17,400.00
ш	107	REMOVE AND REPLACE ASPHALT	\$	60.00	SY	150	SY	\$ 9,000.00
TILE	108	TRAFIC CONTROL	\$:	5,000.00	LS	1	LS	\$ 5,000.00
			CO	NSTRUCT	TION SU	JBTOTAL		\$ 362,530.00
			Con	ntingency	(10%)			\$ 36,253.00
			COI	NSTRUCT	TION TO	TAL		\$ 398,783.00
			Eng	r. & Cons	t. Obser	vation (25%	<u>,</u>	\$ 99,695.75
			TOT	AL DISTR	RICT CO	ST		\$ 498,478.75



Date:	5/7/2018				
Work Order #:	WO00000211				
Drainage District:	Drainage Districts \DD	148			
Sec-Twp-Rge:	07-89-19	Qtr Sec:	NW SE		
Location/GIS:	89-19-07-400-001				
Requested By:	Bill Ibeling				
Contact Phone:	(641) 373-1732				
Contact Email:		II			
Landowner (if different):					
Repair labor, material	fix right away, wait un	til fall to re			
Repaired By:				Date:	
Please reference work	order # and send stat	ement for	services to:	Hardin County Auditor's Office Attn: Drainage Clerk 1215 Edgington Ave, Suite 1 Eldora, IA 50627 Phone (641) 939-8111 Fax (641) 939-8245	
For Office Use Only					
Annroyed:				Date	



Auditor's Office Hardin County 0 0.0275 0.055

0.22 Miles

Date: 5/7/2018

1000-891908100012 nith, Kenneth E Smith, Mary C 10.41 acres 31524 110th St 1000-89/1908300002 Smith, Kenneth E Smith, Mary C 38.82 acres 31524 110th St 2.72 acres 1000-891907400002
Rameyer, Marie K Revocable Trust, etal-1/2 Knipfel, Patricia K-1/3; Rameyer, Robert-1/6
2121 Beaver Ave 1000-891907400004 Rameyer, Marie K Revocable Trust, etal-112 Knipfel, Patricia K-1/3; Rameyer, Robert-1/6 38-38 acres 2121 Beaver Ave D.D. No. 148 S.D.D MAIN (OInch) Bonewitz, Beverly 1000-891907400001-Ibeling, Will Ibeling, Jole 35.94 acres 10123 S Ave 1000-891907200003 Ibeling, Will Ibeling, Jole 18.02 acres 10123 S Ave ing, Nancy K Growden-Pranta Cheryl 38.33 acres 710 College Ave P.D. Box 606

The Data is provided "as is" without warranty or any representation of accuracy, timeliness or completeness. The burden for determining accuracy, completeness, timeliness, marchantability and fitness for or the appropriateness for use ests solely on the requester. Hardin County makes no warranties, express or implied is to the use of the Data. There are no implied warranties of merchantability or fitness for a particular purpose. The requester acknowledges and accepts the limitations of the Data, including the Parta is dynamic and is in a constant state of maintenance, correction and update. Cadastral Data represents land ownership, but does not define it. This Data does not replace a legal survey.

#148

Repair Summary:

- Per the direction of the District Trustees, CGA contacted landowner to see which style of intake (HDPE Hickenbottom or precast concrete) they wanted for a replacement for the broken intake in the NW¼ SE¾ Section 7, Township 89 North, Range 20 West. Landowner selected the HDPE Hickenbottom style.
- Removed existing intake and found that intake was offset from the Main tile, but was connected to Main tile with HDPE tile. Excavated hole further for the new Hickenbottom intake.
- Installed HDPE tee and connected said tee to the existing HDPE tile with factory joint and fast setting concrete.
- Installed intake riser on tee and lined excavated hole with engineering fabric.
- Filled lined hole with 3-inch rock nearly to surface level and fine graded around intake with on-site soil.
- Removed old concrete intake from site.

Contractor Time and Materials (spent while CGA was on-site):

See attached Tabulated Contractor Time and Materials Sheet.

Additional Actions Recommended:

None at this time.



Tabulated Contractor Time and Materials

Date	Totals	11/1/2018	11/14/2018
Workman (hrs)	6	3	3
Backhoe (hrs)	3	1.5	1.5
8"x8"x8" HDPE Tee (ea.)	1	1	
8" HDPE riser (ea.)	1	1	
Engineering Fabric	Yes		
3" Drainage Stone	Yes		
Fast setting concrete	Yes		



PROJECT NUMBER: 6952 COUNTY, ROUTE, ROAD: 5 AVE LOCATION: DD-144	DAYS OF WEEK: SHEET NO. SMT WTFS OF Z
DESCRIPTION OF WORK AND MATERIAL USED FOR NAME, ITEM NO. AND LOCATION	EACH OPERATION, INCLUDING CONTRACTOR/SUB
9:00am - Avride at site	contrator thosat arrived xet
went and set up menument 8056 \$057	shot 3 more county Mon.
8072 8073	
- also set control acrevage Drive way	point in Field Drive N. 06
	IR3/2 /1 Flush &
9:30- 2 mm (vew showed c	ep with Beck Hoe
- Removed old intoke o Contented to intoke - installed Factory Tee	nd Found Single Wall HOPE. 6'48'X8' with Risedon
I Certify that the work described in this report was incorporat Observer's Signature: Reviewed by:	ed into this contract unless otherwise noted. Date Prepared: Engineer

DATE:

2018-11-01

Date Reviewed

CONSTRUCTION ENGINEERING

OBSERVATION REPORT		
PROJECT NUMBER: 6952	DAYS OF WEEK:	S MT WTFS
PROJECT NUMBER: 6952 COUNTY, ROUTE, ROAD: 5 AVE	— SHEET NO.	OF
LOCATION: $D - 148$		
DESCRIPTION OF WORK AND MATERIAL USED NAME, ITEM NO. AND LOCATION	FOR EACH OPERATION, INC	CLUDING CONTRACTOR/SUB
(-)		
C2.	/	
1.5	(6P3 +2)	
		4
		· · · · · · · · · · · · · · · · · · ·
	/	
	4	1
11-00- Done with Repair for the D		loce Rock oround intoly
I Remove old intoke Loom	Site-	
totals 2 mon (vew -	1 1	
Back those -	[i] hour	······································
Exe"xe" tee -	1	
Fus, Fibreit - 1		
ing, that		
		······································
I Certify that the work described in this report was income		
Observer's Signature:	Date Prepared:	2018-11-02
Reviewed by:	Engineer	

DATE:

2018-11-01

Date Reviewed

CONSTRUCTION ENGINEERING









CONSTRUCTION ENGINEERING OBSERVATION REPORT	DATE:	2018-11-44
PROJECT NUMBER: 695 7 COUNTY, ROUTE, ROAD: DD+148 LOCATION:	DAYS OF WEEK: — SHEET NO. —	SMTWTFS OF
DESCRIPTION OF WORK AND MATERIAL USED IN NAME, ITEM NO. AND LOCATION	FOR EACH OPERATION, INCL	UDING CONTRACTOR/SUB
38° wordy	/ 5unny	
12:00 pm - Arrivel on Sit	,	withe Belk ho
2. 1	road intake pipe	
- Regtoding around	intoke	
1:30 pm - Finshed Intote	+ · vernoved old	in take
1, 5 - 10 - 170300 4 +010/00	y per ad the	7 11000
		and the second s
total time! 24	nan Cvew - x 1.5 hr	2 3 hc
t	Buch Hoe X1.7 hi	= 1.5hi
	·	
	·····	
	,	
		=
		
I Certify that the work described in this report was incor		
Observer's Signature:		11-14-2018
Reviewed by:	Engineer	

Date Reviewed









```
6952 2018-11-01ZS.txt

1,3659080.549,5022163.634,1188.926,IR 34 CPT

2,3657563.044,5020032.096,1128.794,TOP TILE 8 INCH

3,3657561.154,5020032.031,1129.332,INTAKE

4,3657813.757,5021610.551,1130.338,TOP TILE BLOWOUT

5,3657810.501,5021614.745,1126.682,TOP 24 VCP

6,3657810.895,5021627.349,1126.558,TOP 24 VCP

7,3657890.313,5022338.901,1130.759,HEADWALL

8,3657890.133,5022339.292,1130.778,HEADWALL

9,3657894.422,5022341.526,1130.723,HEADWALL

10,3657894.648,5022341.174,1130.720,HEADWALL

11,3657896.453,5022342.161,1128.711,HEADWALL

12,3657896.170,5022342.548,1128.720,HEADWALL

13,3657916.375,5022353.112,1129.426,HEADWALL

14,3657917.445,5022353.984,1130.601,HEADWALL

15,3657917.610,5022353.667,1130.590,HEADWALL

16,3657916.278,5022353.508,1129.538,HEADWALL

17,3657921.696,5022356.226,1130.647,HEADWALL

19,3657898.743,5022344.895,1123.815,24 FL

20,3657899.090,5022345.751,1123.642,BOTTOM

8056,3666063.240,5016956.410,1145.800,GPS 8056

8056_GNSS,3666063.240,5016956.410,1145.800,Autonomous Setup

8057,3650565.102,5016949.204,1139.956,GPR 8057

8072,3650774.512,5032816.304,1197.856,GPS 8072

8073,3666060.041,5035470.186,1121.852,GPS 8073
```

 $d = 1 \dots q$

#26

Investigation Summary:

- Utility company (Radcliffe Telephone Company) requested to pass fiberoptic cable under the Main Open Ditch
 of Drainage District #26. Said crossing took place on the south side of Hwy D41, located in the NW¼ Section 32,
 Township 88 North, Range 22 West.
- The contractor completing said work located the path and depth of the cable boring in the under the Main Open Ditch, with depths being 10± feet below said Main Open Ditch.
- Shot existing flowline of Main Open Ditch. When compared to the utility locates, utility is 9.9 feet to 10.6 feet below the existing flowline.
- The depth of silt in said Main Open Ditch was not determined from historical records. However, should a cleanout occur, the 9.9 feet to 10.6 feet of depth indicated that the cable should be well below the original design flowline.

Contractor Time and Materials (spent while CGA was on-site):

None recorded. All work was completed by contractor under Heart of Radcliffe Telephone Company's employ and CGA was not on-site while work was being completed.

Additional Actions Recommended:

No signage was installed by utility company since utility was installed in road ditch. Either they need signage installed or said requirement waived by the District Trustees



Applicant:	Ed Drake			
Contact Email:	edrake@radcliff	etelephone.com		
Contact Phone:	(515) 899-2341	. 445		
Utility Type:	Communications	S		
Drainage District:	Drainage District	ts \DD 26 (51049)		
Description of Works	202 Isabella St. Radcliffe, IA 502: Installing fiber of (Call Dave Nelsor	30 otic cable to new residence I n with approval. (641) 640-0	located at 13180 Co Hwy D41. 395	
County Drainage Dis Beneath Established	stricts, subject to Drainage Distric	8.186, approval is hereby re naintain utilities on, over, a the attached Requirements	equested for the right, privilege and across or beaneath established Hardin of Construction On, Over, Across or aid requirements shall be across of	
Applicant Sign	ature		Date	
Submit Form and Loc	cation Plan To:	Hardin County Auditor's O Attn: Drainage Clerk 1215 Edgington Ave, Suite Eldora, IA 50627 Phone (641) 939-8111 Fax (641) 939-8245 drainage@hardincountyia.	1.	
For Office Use Only				
Application Approva	al:			-
By:		•	Data	
	hairman, Acting as Drainag	ge District Trustee	Date:	-
	APPRO	OVED PERMIT #20:	18-13	




1215 EDGINGTON AVE., SUITE 1 ELDORA, IA 50627 (641) 939-8108

HARDIN COUNTY DRAINAGE DISTRICT UTILITY PERMIT APPLICATION

Applicant:	Company Name
	Address St.
Applicant Contact:	City State Zip ED DRAWE (\$15)899 - 2341 Name Phone Collake@ radcliff= telephone (Con
Utility Type:	BUTY FIBER OFFICE CABLE
Drainage District(s) Cro	ssed:D
Facilities Crossed (spec	ific tile, open ditch): _ ಉ೦ಉ೬
Description of Work:	INSTALL FIRM OFFIC CADLE TO NEW PRESIDENCE
(Location plan of proposed utility must be attached.)	THE RESIDENCE
allauneu Reguirements i	Date
Application Approval:	For Office Use Only
By:	irman, Acting as Drainage District Trustee Date:
	APPROVED PERMIT #: 2018-13

Beacon[™] Hardin County, IA



Disclaimer: The maps included in this website do not represent a survey and are compiled from official records, including plats, surveys, recorded deeds, and contracts, and only contain information required for government purposes. No warranties, expressed or implied, are provided for the data herein, its use or its interpretation. Hardin County assumes no independently verified.

Date created: 10/9/2018 Last Data Uploaded: 10/8/2018 6:35:21 PM

Developed by Schneider

CONSTRUCTION ENGINEERING OBSERVATION REPORT	DATE:	11/5/18
PROJECT NUMBER:	DAYS OF WEEK	SMTWTFS
COUNTY, ROUTE, ROAD:	SHEET NO.	OF
LOCATION: DY AND OPEN SITCH #26		•
1291 AND OPEN SITELL 26		
DESCRIPTION OF WORK AND MATERIAL US. NAME, ITEM NO. AND LOCATION		•
Cia Uny,	DRIZZIE, I"RAIN REG	
SET & ON 26008, 98 IR IN FIRM	JOB SINE, NO ANSWER,	See #GO-GS
DEL A ON GOODS / 8 III IN DEGO	CRISE, VOR HULL.	0467 00-60
FLARA OPTIC HAS 10'+ OF C	OVER FROM \$ OF DOZI	<u> </u>
······································		
-		
No SIGNS FOR	FIBRE COIL	
	The College	
LOOKING NORTH	(upstream) on S. Tw I	DHI J
*63		
1133,5 <u>H</u> - 23.6		·
1109514	#60	-18.50 -18.50
		//09,53
1121.68	-12,31 -12,30	·
17.08 F.O.	1109.60	
£. 1119.72 F	1119, 20 €	-
1109.94	0 0	
(109.08 F.O.	1109.60 1109.	53
-	1	
4:00 P.M., STEUR NELSON COLLED	BACK AND WANTED TO	Know IF FLAGS WIRE
SAU UP, AND IF AMY QUESTIONS,	ALSO JE THERE WAS 10	CUEARANCE, THERE IS.
Certify that the work described in this report was in	corporated into this contract un	less otherwise noted.
Observer's Signature:	Date Prepared:	11/5/18
Reviewed by:	Engineer	
		Date Reviewed .

```
5055 DD26 11-5-18RB.txt
   1,3602878.030,4947844.310,1135.050,HCGPS 8015
   1_GNSS,3602878.030,4947844.310,1135.050,1
  1_GNSS,3602878.030,4947844.310,1135.050,1
2,3586774.843,4946810.299,1151.546,HCGPS 8014
3,3602802.970,4951422.312,1125.773,nw prop cor
3_GNSS,3602802.970,4951422.312,1125.773,3
4,3606791.517,4946863.103,1127.637,tcp-3/4" rod
4_GNSS,3606791.517,4946863.103,1127.637,4
5,3602867.580,4951375.198,1127.899,CP 5 58IR
5_GNSS,3602867.580,4951375.198,1127.899,5
6_3610519_485_4946895_209_1152_180_cp_6.58_ir
   6,3610519.485,4946895.209,1152.180,cp 6 58 ir 6_GNSS,3610519.485,4946895.209,1152.180,6
 6_GNSS,3610519.485,4946895.209,1152.180,6
7,3606246.397,4946915.013,1116.938,18" beehive-gs
8,3606246.115,4946915.636,1115.234,18" beehive-f1
9,3606241.849,4946914.634,1115.972,top 30" clay
10,3606242.647,4946916.080,1115.735,top 8" clay
11,3606225.829,4946910.042,1118.166,f1 road ditch
12,3606240.836,4946912.524,1118.103,f1 road ditch
13,3606256.863,4946912.524,1118.347,f1 road ditch
  14,3606272.242,4946912.696,1118.549,f7
                                                                                                                                          road ditch
14,36062/2.242,4946912.696,1118.549,11 roau of 15,3606205.689,4946899.186,1123.644,eg 16,3606240.149,4946898.649,1123.917,eg 17,3606269.499,4946899.315,1124.040,eg 18,3606292.452,4946896.142,1124.152,eg 19,3606293.340,4946896.455,1124.194,brg deck 20,3606308.982,4946896.270,1124.083,brg deck 21,3606308.722,4946879.578,1124.211,brg deck 22,3606293.051.4946879.682.1124.231.brg deck
  22,3606293.051,4946879.682,1124.231,brg deck
  23,3606292.566,4946897.991,1124.617,top wood wing
25,3606283.754,4946897.991,1124.617,top wood wing 24,3606283.754,4946902.654,1124.480,top wood wing 25,3606309.492,4946898.070,1124.476,top wood wing 26,3606311.910,4946900.233,1124.435,top wood wing 27,3606318.095,4946902.591,1124.368,top wood wing 28,3606309.857,4946896.318,1124.070,eg 29,3606328.368,4946899.253,1123.814,eg 30,3606357.134,4946900.293,1123.404,eg 31,3606358.348,4946910.445,1118.542,fl road ditch
  31,3606358.348,4946910.445,1118.542,f1
                                                                                                                                          road ditch
 32,3606336.107,4946909.735,1118.607,fl road ditch 33,3606321.274,4946910.043,1118.200,fl road ditch
 35,3606359.630,4946889.616,1123.543,c
35,3606326.362,4946888.311,1124.032,c
36,3606300.361,4946887.541,1124.333,c
37,3606267.549,4946887.987,1124.238,c
38,3606215.699,4946888.018,1123.985,c
 39,3606184.022,4946887.132,1123.952,c
40,3602841.034,4949464.725,1132.668,scf sq 348822
 41,3606710.361,4939007.626,1119.050,topcmp
 42,3608094.692,4941353.659,1124.733,s bore
42,3608094.692,4941353.659,1124.733,s bore 43,3608150.308,4941436.658,1124.513,n bore toppipe 44,3610586.607,4941990.546,1131.227,top mh 4 nrim 45,3610845.524,4942501.851,1134.563,top 12" vcp 46,3610823.334,4942488.273,1134.477,top 12" vcp 47,3608387.331,4941777.152,1129.708,6" clay tile 48,3610737.584,4942328.948,1132.146,top 12" vcp 49,3611373.228,4942790.146,1136.847,top 12" vcp 50,3612142.727,4943189.974,1140.142,top 12" vcp 51,3610996.037,4942596.772,1132.586,top 6" vcp 52,3618348.222,4944601.880,1149.772,top new tile 53,3618659.376,4938195.436,1155.296,check shot
 53,3618659.376,4938195.436,1155.296,check shot 54,3611090.629,4936254.774,1126.285,rip rap area 55,3611072.496,4936267.281,1126.679,rip rap area
 56,3618601.977,4936840.165,1155.075,34 irs
57,3618234.727,4936491.155,1149.511,34 irs
 58,3618234.983,4936838.154,,calc prop corner
```


```
5055 DD26 11-5-18RB.txt
  59,3618692.654,4941643.290,1154.610,IRS 1/2
60,3608081.535,4936596.276,1128.028,GS FIBEROPTIC-18.5
61,3608082.858,4936574.894,1122.310,GS FIBEROPTIC-12.7
62,3608081.851,4936573.977,1119.503,TOE FL
63,3608080.390,4936521.548,1133.541,GS FIBERLOCATE-23.6
  64,3608083.160,4936546.698,1121.677,GS FIBERLOCATE-12.6
  65,3608088.765,4936544.729,1119.716,TOE FL
  1000,3601896.395,4952104.849,1110.976,bm-x on nw cor
  1001,3601651.219,4946826.693,1115.370,bm-x on nw cor 1002,3602875.907,4942942.778,1122.602,bm-x on nw cor 1003,3601691.196,4951381.721,1100.549,edge ditch 1004,3601703.919,4951377.476,1105.582,top bank 1005,3601688.649,4951370.118,1100.414,edge ditch
  1006,3601688.168,4951362.894,1100.356,edge ditch
  1007,3601692.992,4951355.846,1103.234,edge ditch
  1008,3601697.302,4951351.694,1104.678,edge ditch
 1009,3601697.302,4951351.694,1104.678,edge ditch 1009,3601693.827,4951339.434,1104.964,edge ditch 1010,3601688.711,4951334.312,1104.311,edge ditch 1011,3601683.435,4951336.305,1101.730,edge ditch 1012,3601679.268,4951337.197,1099.812,edge ditch 1013,3601672.739,4951314.795,1100.132,edge ditch 1014,3601670.791,4951310.531,1098.187,edge ditch 1015,3601665.018,4951396.564,1098.630,edge ditch
  1015,3601665.018,4951296.564,1098.630,edge ditch
  1016,3601661.090,4951280.461,1098.318,edge ditch
  1017,3601675.920,4951275.199,1106.001,top bank
 1017,3601673.920,4931273.199,1106.001,top bank
1018,3601683.528,4951302.484,1106.117,top bank
1019,3601688.340,4951324.956,1105.742,top bank
1020,3601694.038,4951336.567,1105.197,top bank
1021,3601701.928,4951365.753,1105.542,top bank
1022,3601705.268,4951380.716,1105.690,top bank
1023,3601734.668,4951356.560,1104.824,top bank
  1024,3601719.591,4951332.412,1105.298,top
  1025,3601715.290,4951321.497,1106.021,top
 1026,3601706.025,4951302.853,1105.246,top
1027,3601696.807,4951279.934,1105.481,top bank 1028,3601710.514,4951267.317,1104.571,top bank 1029,3601734.501,4951261.584,1104.522,top bank 1030,3601692.387,4951280.333,1105.748,gs 1031,3601700.071,4951309.470,1105.426,gs
 1032,3601703.342,4951320.995,1106.314,gs
 1033,3601706.380,4951329.161,1106.495,gs
1034,3601709.414,4951341.003,1105.707,gs
1034,3601709.414,4951341.003,1105.707,gs
1035,3601716.860,4951364.510,1105.662,gs
1036,3601741.964,4951353.511,1103.777,toe
1037,3601731.884,4951329.823,1103.357,toe
1038,3601725.044,4951319.097,1102.600,toe
1039,3601723.418,4951313.136,1102.304,fl
1040,3601720.372,4951307.846,1102.656,toe
1041,3601730.017,4951294.851,1103.053,toe
 1042,3601724.804,4951274.933,1104.278,top bank
 1043,3601712.196,4951261.565,1104.529,gs
1043,3601712.196,4951261.565,1104.529,gs
1044,3601734.304,4951293.894,1103.491,gs
1045,3601738.230,4951298.767,1102.859,f1
1046,3601740.977,4951302.336,1103.771,gs
1047,3601731.017,4951310.503,1102.985,gs
1048,3601757.471,4951349.577,1103.808,gs
1049,3601790.459,4951327.347,1103.971,gs
1050,3601763.811,4951302.498,1104.390,gs
1051,3601756.797,4951290.726,1103.884,gs
1052,3601756.124,4951288.043,1102.858,f1
1053,3601752.629,4951284.482,1104.208,gs
1054,3601741.579,4951263.066,1104.582,gs
1055,3601729.766,4951241.689,1104.813,gs
```

Page Z



Drainage Utility Permit ApplicationHardin County

Applicant:	Chad Reinholdt	
Contact Email:	c.reinholdt@midlandpower.com	
Contact Phone:	(515) 370-1485	
Utility Type:	Electric	
Drainage District:	Drainage Districts \DD 124	
Description of Work:	DD 124 - Boring D41 for new house on north side of road.	
	Midland Power Coop 1005 E Lincoln Way Jefferson, IA 50129	
County Drainage Dis Beneath Established	act, operate and maintain utilities on, over, across or beaneath established Hardin stricts, subject to the attached Requirements for Construction On, Over, Across or d Drainage Districts. Failure to comply with said requirements shall be ground for ermit by the Hardin County Board of Supervisors. Date	
Submit Form and Lo	Attn: Drainage Clerk 1215 Edgington Ave, Suite 1 Eldora, IA 50627 Phone (641) 939-8111 Fax (641) 939-8245 drainage@hardincountyia.gov	
For Office Use Only	· · · · · · · · · · · · · · · · · · ·	
Application Approv	val:	
By:	Date:	
Sound of Supervisor	APPROVED PERMIT # 2018-8	



Drainage District:

#124

Investigation Summary:

- Utility company (Midland Power Coop) requested to pass electrical service under the main tile of Drainage District #124. Said crossing took place on the south side of County Highway D41, located in the SW¼ SE¼ Section 27, Township 88 North, Range 20 West.
- The contractor completing the work located and exposed the existing VCP main tile (with aid of lath left by CGA staff).
- The contractor completing the work directionally bored the electrical service at 1 foot ± below the main tile and called CGA while on-site to come observe. Since no notice was provided and CGA staff was unavailable, contractor e-mailed pictures to CGA (copies attached) and said that they could uncover everything again if needed when time was available.

Contractor Time and Materials (spent while CGA was on-site):

None recorded. All work was completed by contractor under Midland Power Coop's employ and CGA was not onsite while work was being completed.

Additional Actions Recommended:

- Based on the e-mailed pictures, it is clear that the directional boring was under the main tile, but it is hard if
 not impossible to determine if the 1 foot of clearance was achieved or not. Either everything needs to be
 uncovered again or the requirement of on-site verification waived and replaced by the pictures by the District
 Trustees.
- Since CGA staff was not on-site, it is unknown if signage was installed by the utility company or not since the main tile is at the toe of the road foreslope. Either they need correct signage installed or said requirement waived by the District Trustees.
- CGA recommends repairing the blowouts/sinkholes in the south ditch of County Highway D41. Also, there are trees and brush around the main tile outlet that should be removed.






1215 EDGINGTON AVE., SUITE 1 ELDORA, IA 50627 (641) 939-8108

HARDIN COUNTY DRAINAGE DISTRICT UTILITY PERMIT APPLICATION

Applicant:	Midhad Power Cooprative	
	1005 E Lincoln Way	
	Address Seffenson TA 56129 City State Zip	
Applicant Contact:	And Harrist 515 370 - 1	1485
	Email Email	
Utility Type:	Underground Electric	
Drainage District(s) Cros	00 1011 11	
Facilities Crossed (spec	cific tile, open ditch): DD 124 Main Tile	
Description of Work:	Boring Dyl for new house	on
(Location plan of proposed utility must be attached.)	Abrith Side of Road	
attached Requirements with said requirements so Applicant Signat Submit Form and Location	Hardin County Auditor's Office Attn: Drainage Clerk 1215 Edgington Ave, Suite 1 Eldora, IA 50627 Fax (641) 939-8225 drainage@hardincountyia.gov	ect to the
Application Approval: By: Board of Supervisor Ch	hairman, Acting as Drainage District Trustee	T Gillo 22
	APPROVED PERMIT #: 2018-8	



Lee Gallentine

From:

Chad Reinholdt <c.reinholdt@midlandpower.coop>

Sent:

Wednesday, October 31, 2018 9:48 AM

To:

Lee Gallentine

Subject:

RE: DD 124 - Utility Permit 2018-8

Lee,

I guess I'm sure on the schedule and even if they were going to do that to be honest, the best place to go on this is just give Barry a call and see what his schedule is, but I will tell you those guys are pretty busy right now it might be awhile before they get to that. Let me know if you have any questions, Ill check around to see if anyone toke any pictures of the job and ill forward them to you if they were taken.

Thanks

Chad Reinholdt

Midland Power Cooperative
Staking Technician
Cell- 515.370.1485
c.reinholdt@midlandpower.coop
1005 E. Lincoln Way, P.O. Box 420, Jefferson, IA 50129
(515) 386-4111 | Fax: (515) 386-2385
www.midlandpower.coop | Like us on Facebook!

CONFIDENTIALITY NOTICE: This communication contains privileged or other confidential information. If you are not the intended recipient or believe you have received this communication in error, please reply to the sender indicating that fact and delete the copy you received. In addition, you should not print, copy, retransmit, disseminate, or otherwise use the information contained in this message.

Midland Power is an equal opportunity provider and employer.

From: Lee Gallentine < LGallentine@cgaconsultants.com>

Sent: Friday, October 26, 2018 12:24 PM

To: Chad Reinholdt <c.reinholdt@midlandpower.coop> **Cc:** 'Tina Schlemme' <TSchlemme@hardincountyia.gov>

Subject: RE: DD 124 - Utility Permit 2018-8

Chad,

Barry from your company called a few weeks ago while they were performing the utility installation and left a message. When I called him back later in the day, he indicated that they found the tile and bored the utility more that 1' below it, but the excavation was covered up. I understood and we wouldn't have had a surveyor available to go into the field with that short of notice. I did ask him when he would have everything uncovered again, but he didn't know.

To try to get this project finished out, I had a couple of questions:

- Did anybody from your company take some pictures during the installation? If so, can you forward those to me?
- Do you know your schedule to uncover the tile and expose/locate with depths your utility?

Just let us know.

Lee Gallentine

From:

Chad Reinholdt <c.reinholdt@midlandpower.coop>

Sent:

Thursday, November 08, 2018 1:51 PM

To:

Lee Gallentine

Subject:

Tile Pictures

Lee,

Hopefully these will work for you one is of the pipe we put in and the other one is the bore head under the Tile. Our wire and pipe are under the county's tile approx. one foot

Chad Reinholdt

Midland Power Cooperative
Staking Technician
Cell- 515.370.1485
c.reinholdt@midlandpower.coop
1005 E. Lincoln Way, P.O. Box 420, Jefferson, IA 50129
(515) 386-4111 | Fax: (515) 386-2385
www.midlandpower.coop | Like us on Facebook!

CONFIDENTIALITY NOTICE: This communication contains privileged or other confidential information. If you are not the intended recipient or believe you have received this communication in error, please reply to the sender indicating that fact and delete the copy you received. In addition, you should not print, copy, retransmit, disseminate, or otherwise use the information contained in this message.

Midland Power is an equal opportunity provider and employer.

From: Barry Munson

Sent: Wednesday, November 7, 2018 10:06 AM

To: Chad Reinholdt < c.reinholdt@midlandpower.coop>

Subject:






OBSERVATION REPORT		
PROJECT NUMBER:	DAYS OF WEEK:	SMTWTF
COUNTY, ROUTE, ROAD:	SHEET NO.	· , OF (
DD 124	•	•
LOCATION: DAI AND SEE TO FAST		. *
DESCRIPTION OF WORK AND MATERIAL USED FO	R EACH OPERATION, INCL	UDING CONTRACTOR/SU
NAME, ITEM NO. AND LOCATION		
TOUND 24" comp FLOWING FAST AND I	TUZE, SUEKING AIR. (1)	JURED UPSTREAM
ON THE ROUTE, FOUND MUSTIPLE BROW- OUTS	4' SEEP @ TOR OF D	11 Bism on
SOUTH SIDE Huy. SET TATH @ BLOW-OUTS, I		
TAUSED TO FARMER ON 4X4 THAT WAS BORN AN		
THE was ON S SIAN AND CROSSED TO N S		Swals IN FIRED.
TOT HOLD C TON OF HUY DAY TO TIMP THE		
		•
· · · · · · · · · · · · · · · · · · ·		
Burning Sine	24	J
WICHING THE	The state of the s	
Sy New ELEC. BORR ROUTE	(C)	•
DA SEE	the contract of	
SIRT LATH		041
		·
PP Daw-outs	Zquema	
CEDAR POST + LIRON POST		
GEDHIC TOST 7 2 TRANTOST		
	BRUSH + TREES	
DRAINAGE DIST. NEEDS TO FIX SUCK H	CLES AND MAINTAIN	REGS @ OUTLET.
<u> </u>		
I Certify that the work described in this report was incorporate	ted into this contract unless oth	etwise noted.
Observer's Signature:	Date Prepared:	19/18
Reviewed by:	Engineer	* ·
	•	Date Reviewed

DATE:

CONSTRUCTION ENGINEERING







Drainage District:

H-F 1

Crossing Investigation Summary:

- Utility company (Winnebago Cooperative Telecom Association) requested to pass fiberoptic cable above (approved per District Trustees' approval) Lateral 1 tile in the NW¼ NW¼ Section 6, Township 89 North, Range 21 West. Said crossing is on the southeast side of Highway 65.
- The contractor completing said work located and exposed the top of the VCP Lateral 1 tile. CGA shot the same.
- The contractor completing said work also located the path and depth of the cable boring in the vicinity of the Lateral tile. CGA shot the same. When compared to the tile locate, utility is 4½ feet ± above the top of the Lateral tile.

Contractor Time and Materials (spent while CGA was on-site):

None recorded. All work was completed by contractor under Winnebago Coop Telephone Association's employ and CGA was not on-site while work was being completed.

<u>Additional Actions Recommended:</u>

Signage installed was not in accordance with the permit requirements. Either they need proper signage installed or said requirement waived by the District Trustees.





2223 Emaiwaron Avr., Scirr 2 Econs., 1A 50627 76417 939 #10#

HARDIN COUNTY DRAINAGE DISTRICT UTILITY PERMIT APPLICATION

Applicant	Winnebago Cooperati	ve Telecom Association	
Conference on the second by	Company Name		AMAZON BOOK BOOK BOOK BOOK BOOK BOOK BOOK BO
	704 E Main St		
	Address		MINISTER CONTRACTOR CONTRACTOR CONTRACTOR CONTRACTOR CONTRACTOR CONTRACTOR CONTRACTOR CONTRACTOR CONTRACTOR CO
	Lake Mills	lowa	50450
	City	State	Zip641 210 5809
Applicant Contact	David Arneson		(641
	Name		Phone
	DavidArneson@WCTA	itel.com	
	Email		
Utility Type	Fiber Optic Cable		and control of MA Among copy, phy.
Drainage District(s) Cro	DD F-H1		
Facilities Crossed (spec	officitile open ditch)	Tile	
Description of Work	Bury Fiber Optic Cable	e from Mallard Ave and Hardin R	d going South 1000ft on the
(Location plan of proposed utility must be attached)	East side of Mallard Av	ve then East 500ft.	
operate and maintain ut attached Requirements	lilities on, over, across o for Construction On, O∖	or beneath established Hardin C	e right, privilege and authority to construct ounty Drainage Districts, subject to the ned Drainage District. Failure to comply in County Board of Supervisors
Jane	I (mesor		9-5-18
Applicant Signal			Date
Submit Form and Locati	ion Plan To	Hardin County Auditor's Office Attn. Drainage Clerk 1215 Edgington Ave. Suite 1 Eldora: IA 50627 Fax (641) 939-8225 drainage@hardincountyia.gov	
			For Office Use On ;
Application Approval			
Ву		Date:	
Board of Supervisor C	haiman, Acting as Draina	ige District Trustee	
	APPROVED PE	RMIT #	

Mallard Avenue As Staked

***Coll |
***Co MC-IE/HH43 Hardin Street Hardin Street Driveway Field Drive Road Field Drive 144 HO HB FO(144)(144) BW 61(3) 61(3) 61(3) 61(3) 61(3) 5584 Feet 370 220 IF-CO/HHN IF-CO" UD(3X1.2.00)P UD(2X1-1.25)P Units BFO 144(t) BFO (44(I) UHF(24x36x30) PType MC-F-FHH43 MC-F-FHH43 MC-F-FHH43 MC-FAHH43 MC-FAHH43 IF-CO/HHN IF COMHIN 0.3 1 Inch = 125 Feet From MC-IF/HH44 (MC-IF/HH42)

BUFKE1

ACORD

CERTIFICATE OF LIABILITY INSURANCE

DATE (MM/DD/YYYY) 09/18/2018

THIS CERTIFICATE IS ISSUED AS A MATTER OF INFORMATION ONLY AND CONFERS NO RIGHTS UPON THE CERTIFICATE HOLDER. THIS CERTIFICATE DOES NOT AFFIRMATIVELY OR NEGATIVELY AMEND, EXTEND OR ALTER THE COVERAGE AFFORDED BY THE POLICIES BELOW. THIS CERTIFICATE OF INSURANCE DOES NOT CONSTITUTE A CONTRACT BETWEEN THE ISSUING INSURER(S), AUTHORIZED REPRESENTATIVE OR PRODUCER, AND THE CERTIFICATE HOLDER.

IMPORTANT: If the certificate holder is an ADDITIONAL INSURED, the policy(ies) must have ADDITIONAL INSURED provisions or be endorsed.

-	If SUBROGATION IS WAIVED, subjection that the subjection is subjected in the subject of the subj	to th	e cer	tificate holder in lieu of su	uch end	orsement(s	i).	y require an endo	rsemer	ıt. As	tatement on
PRODUCER FCIS Insurance PO Box 248				CONTACT Mary Peterson							
				PHONE (A/C, No, Ext): (800) 331-1520 FAX (A/C, No): (641)				585-5166			
Fo	rest City, IA 50436				E-MAIL ADDRES	_{is:} info@fc	isinsuranc	e.com			
						IN	SURER(S) AFFO	RDING COVERAGE			NAIC#
					INSURE	RA:Employ	yers Mutua	I Companies			21415
INS	URED				INSURE	₹В:					
	Winnebago Coop Tele Asso	ciati	ion		INSURE	RC:					
	704 E. Main St				INSURER D:						
Lake Mills, IA 50450					INSURER E:						
					INSURE	RF:					
				E NUMBER:				REVISION NUM	BER:		
(E	HIS IS TO CERTIFY THAT THE POLICI NDICATED. NOTWITHSTANDING ANY F CERTIFICATE MAY BE ISSUED OR MAY EXCLUSIONS AND CONDITIONS OF SUCH	PEF	RTAIN ICIES.	ENT, TERM OR CONDITIO , THE INSURANCE AFFOR . LIMITS SHOWN MAY HAVE	N OF A	NY CONTRA	CT OR OTHE	R DOCUMENT WITH		TOT TO	MARIOLITICO
INSF	TYPE OF INSURANCE	ADDI	SUBF	POLICY NUMBER		POLICY EFF (MM/DD/YYYY)	POLICY EXP (MM/DD/YYYY)		LIMIT	s	
A	X COMMERCIAL GENERAL LIABILITY							EACH OCCURRENCE	E	s	1,000,000
	CLAIMS-MADE X OCCUR	Х		5D58267		01/01/2018	01/01/2019	DAMAGE TO RENTEI PREMISES (Ea occurr	D rence)	\$	100,000
								MED EXP (Any one pe		\$	1,000,000
	GEN'L AGGREGATE LIMIT APPLIES PER:							PERSONAL & ADV IN		\$	2,000,000
	POLICY X PRO- X LOC							GENERAL AGGREGA		\$	2,000,000
	OTHER: General Aggregate							PRODUCTS - COMP/6	OP AGG	\$	1,000,000
A	AUTOMOBILE LIABILITY							COMBINED SINGLE L (Ea accident)	LIMIT	\$	1,000,000
	X ANY AUTO			5E58267	04/04/20	01/01/2018	01/01/2019			\$	1,000,000
	OWNED SCHEDULED AUTOS ONLY			0200207		01/01/2010	01/01/2019	BODILY INJURY (Per		\$	
	X HIRED X NON-OWNED AUTOS ONLY							BODILY INJURY (Per PROPERTY DAMAGE (Per accident)	accident)	\$	
	AUTOS ONLY							(Per accident)	-	\$	
A	X UMBRELLA LIAB X OCCUR						***************************************	540U 000UBBBU0	_	\$	10,000,000
	EXCESS LIAB CLAIMS-MADE	Х		5J58267		01/01/2018	01/01/2019	EACH OCCURRENCE	-	\$	10,000,000
	DED X RETENTION\$ 0							AGGREGATE		\$	10,000,000
Α	WORKERS COMPENSATION AND EMPLOYERS' LIABILITY							PER STATUTE	OTH- ER	\$,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
				5H58267	o	01/01/2018	01/01/2019				500,000
	ANY PROPRIETOR/PARTNER/EXECUTIVE OFFICER/MEMBER EXCLUDED? (Mandatory in NH)	N/A						E.L. EACH ACCIDENT E.L. DISEASE - EA EM		\$	500,000
	If yes, describe under DESCRIPTION OF OPERATIONS below							E.L. DISEASE - POLIC			500,000
				<u> </u>				E.L. DISEASE - POLIC	Y LIIVII I	\$	
DES	CRIPTION OF OPERATIONS / LOCATIONS / VEHICL	ES (A	CORD	101. Additional Remarks Schedule	e may be :	attached if more	s enaco ie roquir	od)			
				The state of the s	e, may be t	attached if inore	s space is require	euj			
EF	RTIFICATE HOLDER				CANCE	LLATION					
Hardin County Drainage District					THE	EXPIRATION	DATE THE	ESCRIBED POLICIES EREOF, NOTICE	S BE CAI	NCELLI	ED BEFORE
	County/Drainage District	iict			ACCO	RDANCE WIT	H THE POLIC	Y PROVISIONS.	0		
	1215 Edgington Ave, Suite 1			-							
	Eldora, IA 50627] •		ED REPRESEN	ITATIVE				
		1 to ties 0									

OBSERVATION	N REPORT		
PROJECT NUMBER:	5166.4	DAYS OF WEEK: SHEET NO.	SMTWTFS OF
COUNTY, ROUTE, ROAD:			
LOCATION: H-F1			
DESCRIPTION OF WORK AND NAME, ITEM NO. AND LOCA		— R EACH OPERATION, INC	CLUDING CONTRACTOR/SUB
9:15 am - sot up	GPS at po	int (4) che	chod into post (
- shot	Flags, Pan	+ morts, plus	intoke of Veult
·			·
A	5	65	

N		Hut	
	9 6		1059
		. / / /////	Vault
		1000	
		1 (p+ 56)	
		(Pipe) Q	
	/ 1		Bec Hive
			Intate
	/ P	omt morks	
EL			
GPS # 56 115253 -	1 17712	to pipe	\$ \$ \$P
H57 1153.58-6	1.0= 1149.58	to utility	
	4,45	Clearance	
10:15 - Lett	Site.		
I Certify that the work described in	in this report was incorpor	rated into this contract unless	otherwise noted.
Observer's Signature:	ı P	Date Prepared:	
Reviewed by:		Engineer	
			Date Reviewed

DATE:

CONSTRUCTION ENGINEERING















```
5166.3 2018-10-31zs.txt
  1,3659904.394,4986390.676,1125.823,TOP TILE
  2,3659812.671,4985391.777,1147.616,CPT 3/4 .2DEEP
  3,3659782.051,4985357.458,1147.473,FNL WCP RRTIE/BOTTLECAP
  4,3665691.249,4985363.158,1153.641,GPS MON 8039
  5,3659919.120,4986488.379,1127.498,TOP 34"CLAY TILE
  6,3659920.859,4986503.933,1129.966,GS TILELOCATE 7,3659931.521,4986574.343,1130.277,GS TILELOCATE
 8,3659948.714,4986685.971,1130.961,GS TILELOCATE 9,3659959.924,4986781.495,1131.296,GS TILELOCATE 10,3659972.384,4986876.574,1131.568,GS TILELOCATE
 11,3659987.590,4986964.160,1131.470,GS TILELOCATE
 12,3660063.096,4987044.872,1132.202,GS TILELOCATE
 13,3660142.930,4987089.453,1132.344,GS TILELOCATE
 14,3660210.200,4987114.216,1132.592,GS TILELOCATE
15,3660241.003,4987112.277,1132.334,GS TILELOCATE 15,3660241.003,4987112.277,1132.334,GS TILELOCATE 16,3659914.033,4986445.626,1129.633,GS TILELOCATE 17,3659901.584,4986357.345,1128.837,GS TILELOCATE 18,3659886.931,49862053.617,1129.264,GS TILELOCATE 19,3659880.521,4986202.991,1129.072,GS TILELOCATE 19,3659880.521,4986202.991,1129.072,GS TILELOCATE 19,3659880.521,4986202.991,1129.072,GS TILELOCATE
 20,3659870.128,4986112.721,1128.906,GS TILELOCATE
 21,3659864.739,4986027.615,1127.510,GS TILELOCATE
 22,3659864.760,4985982.186,1127.287,GS TILELOCATE
22,3659865.818,4985900.461,1127.542,GS TILELOCATE
24,3659865.266,4985805.138,1127.240,GS TILELOCATE
25,3659859.922,4985768.026,1127.640,GS TILELOCATE
26,3659838.413,4985723.086,1124.635,TOP CMP
27,3659904.893,4986381.960,1127.247,TOP 34"VCP JOINT/FLASH/FABRIC/CONCCOLAR
28,3659905.504,4986388.045.1127.140.TOP 34"VCP JOINT/FLASH/FABRIC/CONCCOLLAR
 29,3659906.016,4986388.045,1127.140,TOP 34"VCP JOINT/FABRIC/CONCCOLLAR
 30,3659906.590,4986390.973,1127.091,TOP 34"VCP JOINT/FABRIC
 31,3659919.241,4986488.544,1127.544,TOP 34"VCP/36"RCP JOINT/FLASH/FABRIC/CONCCOLLAR
 32,3659919.962,4986494.735,1127.542,TOP 34"VCP/36"RCP JOINT/FLASH/FABRIC/CONCCOLLAR
 33,3659840.466,4985726.616,1121.406,CONC FLOOR
34,3659864.644,4985863.876,1123.096,FL CLAYMAIN
35,3659838.896,4985723.532,1124.708,TOP CMP
36,3659848.982,4985740.595,1124.745,TOP CMP
 37,3659848.848,4985740.725,1125.080,TOP RCP TO CMP
 38,3659850.255,4985748.009,1125.237,TOP RCP JOINT
 39,3659851.428,4985755.881,1125.251,TOP RCP JOINT
 40,3659852.316,4985763.904,1125.302,TOP RCP JOINT
41,3659853.275,4985771.757,1125.379,TOP RCP JOINT 42,3659854.147,4985779.918,1125.410,TOP RCP JOINT 43,3659855.068,4985787.920,1125.410,TOP RCP JOINT 44,3659855.746,4985795.850,1125.484,TOP RCP JOINT 45,3659856.516,49858013.776,1125.537,TOP RCP JOINT 46,3659857.342,4985811.786,1125.693,TOP RCP JOINT 47,3659858.137,4985811.786,1125.693,TOP RCP JOINT 47,3659858.137,4985811.786,1125.712.TOP RCP JOINT 47,4985811.786,1125.712.TOP RCP JOINT 47,4985811.786,1125.TOP RCP JOINT 47,4985811.786,1125.TOP RCP JOINT 47,4985811.786,1125.TOP RCP JOINT 47,
 47,3659858.137,4985819.901,1125.712,TOP RCP JOINT
 48,3659858.899,4985827.792,1125.753,TOP RCP JOINT
48,3659858.899,4985827.792,1125.753,10P RCP JOINI
49,3659859.953,4985835.664,1125.954,TOP RCP JOINT
50,3659861.022,4985843.601,1126.011,TOP RCP JOINT
51,3659862.360,4985851.743,1126.120,TOP RCP JOINT
52,3659863.880,4985859.364,1126.356,TOP RCP JOINT
53,3659849.211,4985739.533,1126.374,CONC COLLAR
54,3659863.881,4985859.418,1126.885,CONC COLLAR
55,3659864.755,4985864.225,1126.707,CONC COLLAR
 56,3665541.950,4985412.455,1152.527,GS -7.4 TO TILE
 57,3665544.736,4985405.705,1153.578,GS FLAG 48 IN DEEP
 58,3665540.862,4985415.081,1152.329,GS FLAG
 59,3665539.122,4985421.310,1152.195,GS FLAG
60,3665537.440,4985426.300,1151.656,GS FLAG 61,3665536.521,4985426.775,1151.734,VULT 62,3665535.649,4985428.358,1151.951,VULT
63,3665538.138,4985429.669,1152.089,VULT
```

Page 1

```
5166.3 2018-10-31zs.txt
64,3665538.959,4985428.051,1151.854,VULT
65,3665523.738,4985398.439,1154.502,GS PAINT MARK
66,3665528.429,4985399.579,1154.427,GS PAINT MARK
67,3665535.106,4985401.917,1154.153,GS PAINT MARK
68,3665541.614,4985404.462,1153.871,GS PAINT MARK
69,3665552.616,4985407.739,1153.693,GS PAINT MARK
70,3665560.038,4985410.085,1153.688,GS PAINT MARK
71,3665568.076,4985413.040,1153.612,GS PAINT MARK 72,3665566.450,4985387.591,1156.276,GS PAINT MARK 73,3665577.533,4985378.066,1157.272,GS PAINT MARK 74,3665588.586,4985375.107,1157.788,GS PAINT MARK
75,3665530.161,4985425.880,1150.909,INTAKE W EDGE 500,3661320.981,4990609.255,1135.662,IR 12 0.3' X
501,3661471.709,4990264.892,1129.956,TOP 12" SW CPP LAT1 TILE LAT 1 (1.08' TOP TO
FL)
502,3661473.994,4990263.400,1129.788,TOP 12" SW CPP LAT 1 TILE (1.08' TOP TO FL)
503,3661469.637,4990265.673,1129.768,TOP 12 SW CPP LAT 1 TILE (1.08 TOP TO FL) 503,3661469.637,4990265.673,1129.933,TOP EXIST COLLPSING 14" CLAY LAT 1 TILE 504,3661478.517,4990346.619,1131.196,TOP EXIST 24" CMP TILE (2.03' TOP TO FL) 505,3661470.143,4990382.375,1133.173,SFP W RR ROW 506,3661468.435,4990404.151,1133.532,FL 34.75" STEEL CASING CULVERT 2005 CONC HDWALL 507,3661476.413,4990278.257,1129.882,EXIST 24" TILE CRUSH START 508,3661469.460,4990524.370,1132.861,FL 34.75" STEEL CASING CULVERT 2005 CONC HDWALL 509,3661315.025.4090611.107,1135.633.FENCE N. S. F. R. ROW
509,3661315.025,4990611.107,1135.632,FENCE N-S E RR ROW
510,3661357.379,4990610.983,1134.650,FENCE N-S E RR ROW 511,3661473.526,4990152.319,1130.914,TOP EXIST 24" CLAY TILE (2.1' TOP TO FL) 512,3661473.430,4990149.619,1130.858,TOP EXIST 24" CLAY TILE (2.1' TOP TO FL)
PLUGGED CONC
513,3659783.042,4985407.784,1147.590,FENCE E-W
514,3661357.220,4990483.801,1140.821,CL E SPUR RR TRACK
515,3661554.572,4990482.128,1140.671,CL E SPUR RR TRACKS
516,3661518.700,4990383.523,1133.295,FENCE N-S W RR ROW
517,3661431.057,4990384.077,1135.323,FENCE N-S W RR ROW
518,3661473.420,4990146.942,1133.715,GS ABOVE TILE
519,3661479.495,4990355.654,1131.745,GS ABOVE TILE
8040,3665637.400,5001108.410,1155.680,GPS8040
8040_GNSS,3665637.400,5001108.410,1155.680,Autonomous Setup
```