



Hardin County Drainage

Drainage Districts \DD 167 (51191)

WO00000208

Work Order Detail Summary

Begin Date: 4/26/2018
Status: Engineer Report - Engineer Creating Report
Description: DD 167 - Blowout in lower end of waterway in NE SE 4-86-20 with "babies" northwest of it. The ground cover over the tile in this area is very shallow.

Requested By: Robert Jenson
Email:
Phone: (641) 849-0341
Landowner: Neil Martin
GIS #: 86-20-04-400-002
Sec-Twp-Rge: 04-86-20 NE SE

Expenses:				
Date	ExpenseCode	Vendor	Description	Amount
9/24/2018	Engineering	Clapsaddle-Garber Assoc	DD 167 ENG SVCS 7/13-9/14	\$274.90
9/28/2018	Engineering	Clapsaddle-Garber Assoc	ENG SVCS 7/13-9/14	\$274.90
10/22/2018	Engineering	Clapsaddle-Garber Assoc	DD 167 ENG SVCS 9/14-10/12	\$964.00
Total:				\$1,513.80

Contract/Estimate:	
Description	Amount

Notes:

Note

5-2-2018 BOS approve work order request and for CGA to investigate. If a simple fix, CGA should continue with hiring a contractor through the lottery system.

7/11-Evidence of blockage. BOS set landowner mtg for 7/25/18 at 11:00 am. Tina to research the history of the DD.

7/25-CGA to create engineer's report with both repair and improvement options. Repair to include a single line repair and replacing both lines into one. Reclassification may be considered when eng rpt is discussed.

10/29/18-Robert Jensen was in and would like the blowout repaired. Crops are out and will have cattle out there in 3 weeks. Blowout is still flagged.