



# Drainage Work Order Request For Repair

## Hardin County

**Date:** 10/29/2018

**Work Order #:** WO00000230

**Drainage District:** Drainage Districts \DD 62 (51092)

**Sec-Twp-Rge:** 15-88-20      **Qtr Sec:** SE NW

**Location/GIS:** 88-20-15-100-004

**Requested By:** Jack Nissly

**Contact Phone:** (641) 648-4285

**Contact Email:** \_\_\_\_\_

**Landowner (if different):** Jean Nissen Trust

**Description:** DD 62 - A lot of water standing in SE corner of SE NW 15-88-20. There has never been a water problem here and they would like to know where lateral 2 tile is exactly and where this land outlets to. Appears tile was relocated with hog farm to SE. Please call Jack when will be out.

**Repair labor, materials and equipment:** \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

**Repaired By:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Please reference work order # and send statement for services to:**  
Hardin County Auditor's Office  
Attn: Drainage Clerk  
1215 Edgington Ave, Suite 1  
Eldora, IA 50627  
Phone (641) 939-8111  
Fax (641) 939-8245

For Office Use Only

**Approved:** \_\_\_\_\_ **Date:** \_\_\_\_\_