

Ms. Becca Junker  
Hardin County Drainage Clerk  
1215 Edgington Avenue  
Suite 1  
Eldora, IA 50627

Ms. Junker:

Re.: Request for Repairs to the Main Drainage Tiles in Drainage District 167

Please place this request before the Board of Supervisors for their consideration and action. Representatives of the owner of parcels 862004400003 and 862004400001 have discovered four sinkholes each approximately 30 inches deep near the location of the main drainage lines as noted in the diagram on the next page. The western most sinkhole opened in 2018, the eastern most last weekend, and the other two in spring of 2019. Representatives also found a half buried section of 8-inch ceramic tile along with ceramic shards near the location indicated in the diagram; the site has been marked (staked) for easy location. The broken/half-buried 8 foot section of tile on the surface is either refuse from an earlier repair of the main, or is evidence that the current main consists of at most only one 8-inch tile near that location. Also, a long ravine has been cut through a grassed waterway just east of the broken/half-buried tile. The ravine at viewing was 1 – 2 feet in depth and extended almost to the eastern boundaries of the parcels.


Thank you for your consideration and action. Please acknowledge receipt of this letter.

Respectfully,

A handwritten signature in black ink, appearing to read "D. R. Bernard".

David R. Bernard, representing Donna Bernard  
2481 NW 87<sup>th</sup> Ave.  
Ankeny, IA  
1.515.965.6788  
drbernardconsulting@gci.net

cc.: Donna Bernard  
Curt Winter



Thick, black lines represent the southwest boundaries of Drainage District 167 in Harding County, IA. Thick gray lines represent the approximate location of the two 8-inch tiles that comprise the main drainage line for the district.