



Drainage Work Order Request For Repair

Hardin County

Date: 7/31/2019

Work Order #: WO00000266

Drainage District: DDs\DD 26 (51049)

Sec-Twp-Rge: 30-88-22 **Qtr Sec:** SE NE

Location/GIS: _____

Requested By: James Sweeny

Contact Phone: (614) 373-3131

Contact Email: jsweeney@cgaconsultants.com

Landowner (if different): David/Annette Sweeney

Description:

DD 26 - Overland water flow is bypassing surface inlet and has created a washout in the north bank of the DD26 main open ditch. Said washout and surface inlet are marked with a fencepost and pvc at each. The washout is approximately 1200 feet upstream of the DD22 Main tile outlet (of which is on the west side of C Avenue). Both the surface inlet and washout are visible via aerial photography on the beacon website.

Repair labor, materials and equipment _____

Repaired By: _____ **Date:** _____

Please reference work order # and send statement for services to:

Hardin County Auditor's Office
Attn: Drainage Clerk
1215 Edgington Ave, Suite 1
Eldora, IA 50627
Phone (641) 939-8111
Fax (641) 939-8245

For Office Use Only

Approved: _____ **Date:** _____