

RELIABLE 1

HEATING | AC | PLUMBING

The 1 You Can Trust

Reliable1
1854 Crescent Drive
Iowa Falls, Iowa 50126
641-648-2327

Invoice 17325677
Invoice Date 11/29/2021
Completed Date 12/22/2021
Customer PO

Billing Address
Hardin County Courthouse
1215 Edgington Avenue
Eldora, IA 50627 USA

Job Address
Hardin County Courthouse
1215 Edgington Avenue
Eldora, IA 50627 USA

Description of Work

Task #	Description	Quantity	Your Price	Your Total
Contract Job	Compressor out on Geo Unit. Pressure tested system, found leak in unit on oil return line, repaired, evacuated system and changed out compressor, accumulator, and inverter board per Mitsubishi request. Also installed suction filter drier with bypass to clean up system.	1.00	\$10,475.05	\$10,475.05
	Materials: Oil acid test kits, Refrigerant copper, fittings, valves, & adapters, R410 Refrigerant, refrigerant disposal fee, nitrogen for testing, vacuum oil, torches, misc, & shop materials.			
	Warranty Parts: (not included in total) Compressor for VRF Unit \$6,923.08- No Charge Inverter Board for VRF Unit \$384.62- No Charge Accumulator for VRF Unit \$1,784.62- No Charge			

FILED

JAN 05 2022

HARDIN COUNTY AUDITOR

0001-49-9100-000-44104
JMA \$10,475.05

Sub-Total \$10,475.05
Tax 0% \$0.00
Total Due \$10,475.05
Balance Due \$10,475.05

Thank you for choosing Reliable1!

This invoice is agreed and acknowledged. Payment is due upon receipt. A service fee of \$35.00 will be charged for any returned checks, and a financing charge of 1.75% per month shall be applied for overdue amounts.

X

11/29/2021

I find and agree that all work performed by Reliable1 has been completed in a satisfactory and workmanlike manner. I have been given the opportunity to address concerns and/or discrepancies in the work provided, and I either have no such concerns or have found no discrepancies or they have been addressed to my satisfaction. My signature here signifies my full and final acceptance of all work performed by the contractor.

X

Pay under protest!

11/29/2021