AGENDA REGULAR DRAINAGE MEETING AUGUST 7, 2019 AT 8:30 AM

- 1. Open Meeting
- 2. Approve Agenda
- 3. DD 22 Discuss, With Possible Action, Change Order
- 4. DD 26 Approve Work Order 266

Documents:

NO DD WO 266.PDF WO 266.PDF WO REQUEST 266.PDF


- 5. DD 143 Discuss, With Possible Action, Unite Private Networks
- 6. Other Business
- 7. Adjourn Meeting



Hardin County Auditor's Office



Date: 7/31/2019






Hardin County Auditor's Office



Date: 7/31/2019





Drainage Work Order Request For Repair Hardin County

Date:	7/31/2019				
Work Order #:	WO00000266				
Drainage District:	DDs\DD 26 (51049)				
Sec-Twp-Rge:	30-88-22	_ Qtr Sec:	SE NE		
Location/GIS:					
Requested By:	James Sweeny				
Contact Phone:	(614) 373-3131				
Contact Email:	jsweeney@cgaconsultants.com				
Landowner (if different):	David/Annette Swe	eney			
Repair labor, materia	DD 26 - Overland water flow is bypassing surface inlet and has created a washout in the north bank of the DD26 main open ditch. Said washout and surface inlet are marked with a fencepost and pvc at each. The washout is approximately 1200 feet upstream of the DD22 Main tile outlet (of which is on the west side of C Avenue). Both the surface inlet and washout are visible via aerial photography on the beacon website. Is and equipment				
Repaired By:				Date:	
Please reference work order # and send statement for services to:			Hardin County Auditor's Office Attn: Drainage Clerk 1215 Edgington Ave, Suite 1 Eldora, IA 50627 Phone (641) 939-8111 Fax (641) 939-8245		
For Office Use Only					
Approved:				Date:	